

**AIRFRAME**

<b>Year Mfr/Div:</b>	2005 / 2005
<b>Registration #:</b>	C6-
<b>Purchase Date:</b>	5/10/2017
<b>Airframe Total Time:</b>	2,718 hrs (As of 5/2/2017)
<b>Landings/Cycles:</b>	1,608
<b>New/Used:</b>	Previously Owned

**ENGINE(S)**

<b>Model:</b>	TFE731-60
<b>On Condition TBO:</b>	No
<b>Maintenance Program:</b>	Honeywell Engines & Systems - MSP Gold
<b>Ser No:</b>	Eng 1 (L): P112573 / Eng 2 (R): P112574 / Eng 3 (L): P112575
<b>Total Time Since New:</b>	Eng 1 (L): 2,718 hrs / Eng 2 (R): 2,718 hrs / Eng 3 (L): 2,718 hrs
<b>Time Between Overhaul:</b>	Eng 1 (L): 5,000 hrs / Eng 2 (R): 5,000 hrs / Eng 3 (L): 5,000 hrs
<b>Cycles Since New:</b>	Eng 1 (L): 1,608 hrs / Eng 2 (R): 1,608 hrs / Eng 3 (L): 1,608 hrs

**AUXILIARY POWER UNIT (APU)**

<b>Model:</b>	Garrett GTCP 36-150F
<b>Serial #:</b>	P570
<b>Total Time Since New:</b>	2,140 hrs
<b>Maintenance Plan:</b>	Garrett/AlliedSignal/Honeywell (MSP/Maintenance Service Plan)

**AVIONICS**

<b>ADF:</b>	Dual Honeywell DF-855
<b>Avionics Package:</b>	Honeywell Primus II
<b>Communication Radios:</b>	Triple Honeywell TR-866B
<b>CVR:</b>	Honeywell SSCVR (120-minute)
<b>DME:</b>	Dual Honeywell DM-855
<b>FDR:</b>	Honeywell SSFDR
<b>FMS:</b>	Triple Honeywell EASy w/dual GPS-90X
<b>Hi Frequency:</b>	Dual Collins HF-9000 w/Honeywell SELCAL
<b>IRS:</b>	Triple Honeywell LASEREF V
<b>Navigation Radios:</b>	Dual Honeywell NV-875A
<b>Radar Altimeter:</b>	Honeywell AA-300
<b>SATCOM:</b>	Universal Aero I 3-channel
<b>Stormscope:</b>	Honeywell LSZ-860
<b>TAWS:</b>	Honeywell EASy EGPWS w/windshear & TCF
<b>TCAS:</b>	Honeywell TCAS-2000 w/change 7.1
<b>Transponder:</b>	Dual Honeywell XS-855A
<b>Weather Radar:</b>	Honeywell Primus 880 color

**ADDITIONAL EQUIPMENT**

<b>Cockpit:</b>	EASy cockpit, dual Honeywell EASy II (baseline) modular avionics units, triple Honeywell AV-900 audio panels, Honeywell EASy multi-function display & communication management function, ELTA ADT 406 ELT (FAA & JAA approved), Meggitt Mark II secondary flight display, cabin temperature mixing valve position indicating system, dedicated maintenance laptop computer w/AC connection kits
<b>Crew Accessories:</b>	Jeppesen ETC
<b>General:</b>	Rechargeable flashlights, dual 12-man life rafts, 115 cubic foot enlarged oxygen bottle, telescopic tow bar, 115-volt AC/60Hz 1200VA inverter
<b>Lights:</b>	Dual Teleflex recognition (fin logo), dual-bulb wing-tip navigation

**INTERIOR**

<b>Passengers:</b>	14
<b>Configuration:</b>	Executive
<b>General:</b>	Beige & almond harmony interior; partial cabin, galley, lav & luggage refurbishment as reported 03/20/2013
<b>Seating:</b>	Beige leather seating, forward 20-inch 4-place club, mid-cabin dining area, aft lounge w/dual 3-place 5-inch manually berthable beige & almond fabric divans, ERDA third crew seat
<b>Refreshment Equip:</b>	Galley w/Starr hot cup, Iacobucci espresso coffee machine, extra-wide TIA high-temperature oven, TIA microwave oven
<b>Cabinetry/Woodwork:</b>	Bird's-eye maple wood veneer, mid-cabin electric hi-lo pedestal table
<b>Entertainment Equip:</b>	Audio International entertainment controls, Honeywell 15-inch LCD monitor, Honeywell 20-inch LCD monitor, eight plug-in receptacles, four Rosen 8.4-inch plug-in monitors, Audio International 2-disc DVD player w/dual infrared remote controls, Honeywell JetMap cabin display w/audio briefing
<b>Accessories:</b>	Satin champagne gold metal plating, mid-cabin divider w/stowable curtain, galley pocket door, eight power outlets
<b>Lavatory:</b>	Forward crew & aft

**EXTERIOR**

<b>Last Done:</b>	2012
<b>Colors:</b>	White w/dual custom gray tail & fin stripes

**MAINTENANCE**

<b>Maintained:</b>	EU OPS 1
<b>Airframe Maint Program:</b>	Unknown
<b>Airframe Tracking Program:</b>	CAMP (Computerized Aircraft Maintenance Program)
<b>Certification(s):</b>	RVSM
<b>Notes:</b>	C-Check c/w 09/2011. Dry Bay Mod SB 329 c/w as reported 11/20/2015. Garrett APU enrolled on MSP Gold. Honeywell Avionics Protection Plan.

















